

Message

From: Nordine, John [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=6F082FB004BA4D818FE3276686C84C63-JNORDINE]
Sent: 10/17/2013 1:16:40 PM
To: Bob Kay [rtkay@usgs.gov]
Subject: FW: Central Wire
Attachments: Techalloy-2012 Fence 2d perp09302013.pdf; Techalloy-2012 Fence 2d perp2 09302013.pdf

Bob, Welcome back to work. Please review and comment.

Respectfully,

John Nordine, CPG, LPG
 U.S. EPA, Region 5
 RCRA Corrective Action Section
 77 W. Jackson Blvd. LU-9J
 Chicago, Illinois 60604

Phone: 312-353-1243
 Fax: 312-385-5338

"The great end of education is to discipline rather than finish the mind; to train it to use of its own powers rather than to fill it with the accumulation of others." Tryon Edwards

"Don't interfere with anything in the Constitution. That must be maintained, for it is the only safeguard of our liberties" Abraham Lincoln

From: Jack Thorsen [mailto:jack@autumnwoodesh.com]
Sent: Wednesday, October 02, 2013 12:19 PM
To: Nordine, John
Cc: Gerald Ruopp
Subject: FW: Central Wire

John:

Steve did 4 fence diagrams for Central Wire of exceedances of MCL from:

- GP-16 - GP-17 - GP-3 - GP-19 - GP-20
- GP-16 - GP-17 - GP-8 - GP-19 - GP-20
- GP-16 - GP-17 - GP-18 - GP-19 - GP-20
- GP-16 - GP-17 - GP-22 - GP-19 - GP-20

If you would share your thoughts with me, I would appreciate it.

Regards,

Jack

*John W. Thorsen, P.E.
 Autumnwood ESH Consultants*

262.237.1130

From: Steven Grant [<mailto:Steve.Grant@grantecc.com>]

Sent: Monday, September 30, 2013 5:41 PM

To: John Thorsen

Subject: Central Wire